



COMPLETION REPORT

1	Name of the work	Improvements to Footpath in 6th Cross road at Vivekananda roads & Other roads at Mallasandra, in ward No. 13, in Shettyhalli Sub Division.		
2	Sanctioned Estimate No. & Date	CE/DD/AA/050/14-15 dt 29/10/14		
3	Head of Account which is chargeable	P-1771		
4	Instrument Order NO. & Date	EE/DD/Wo/336/14-15 dt 31/3/2015		
5	Name Of Contractor	G. Aswathappa, No. 880, 9th Main road, 1st Cross, Hesaraghatta Road, Bhuvaneshwarinagara, T. Dasarhalli, Bangalore.		
6	Time Stipulated for Completion of work	Yes		
a				
b	Delay in Exculation of Work	No		
7	Measurement recorded in	3423/14-15		
8	Check Measurement of the Asst	342201 to 342209		
9	Name of the office/official in charge of the work	AEE/SSD		
10	a) Asst. Eng/junior Eng	Nagabhusan.		
	b) Asst. Exe Engineer	B.L. Taya Lingappa.		
Sanctioned Estimate Amout		Amout Claims As per Actually Vide As per bills	Excess	Savings
18.00 Lacs		16,53,709.00	—	1,46,291.00

- 1) Certified that the above work has been completed within the stipulated time noted in the
- 2) Certified that the contractor has delayed and completed the work for which necessary fine recovered
- 3) Certified that the above work has been executed by the contractor satisfactory in


ASSISTANT ENGINEER.


ASSISTANT EXECUTIVE ENGINEER

ಶಿಕ್ಷಣ ಕುಟುಂಬ, ದಾಸರಹಳ್ಳಿ ಪಾಲಿಕೆ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು.

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾಸರಹಳ್ಳಿ ಪಾಲಿಕೆ, ಬೆಂಗಳೂರು


ಇಂಜಿನಿಯರ್